


## How to replace the rope?



**GRILLON replacement ropes, 2018 models up to 5 meters, are compatible with GRILLON models from January 2010 to May 2018, but this combination is not certified. Explanation:**

Your GRILLON was certified to meet the year 2009 requirements of Directive 89/686, based on the EN 358: 1999 and EN 795: 1996 standards.

With the launch of the new GRILLON in May 2018, the GRILLON ropes (and thus the replacement ropes) have evolved. The new replacement rope, designed for GRILLON released after May 2018, is 11 mm in diameter, whereas GRILLON sold before May 2018 have an 11.5 mm diameter rope.

We performed the tests of the EN 358: 1999 standard with this new rope installed in a pre-2018 GRILLON. The results are in compliance. We could not certify this new combination: GRILLON sold before 2018 with new replacement rope sold after May 2018, for the following reasons:

- Certifications are done before putting products on the market and not for products already sold.
- Regulation 2016/425, which replaces Directive 89/686 for the placing of PPE on the market, requires the manufacturer's name and address to appear on the products, and the Instructions for Use to be modified. We are unable to do this for products already sold.
- The EN 795: 1996 standard has been replaced by EN 795: 2012, which would also require changing the marking and Instructions for products already sold. We are unable to do this for products already sold.